

AD-A264 322



167

①

A NEGATIVE IMPACT REPORT OF A CULTURAL RESOURCES SURVEY OF  
LEVEE MAINTENANCE ITEM No. R-25.3 R.A.C., NEAR CHARLESTON,  
MISSISSIPPI COUNTY, MISSOURI

DTIC  
ELECTE  
MAY 17 1993  
S C D

U.S. Army Corps of Engineers  
Memphis District

Jimmy D. McNeil  
Archaeologist

July 1984

**DISTRIBUTION STATEMENT A**

Approved for public release  
Distribution Unlimited

23 3 14 04 5

93-10849



1280



# ABSTRACT

On 11 June 1984, an intensive cultural resources survey was conducted by the Environmental Analysis Branch of the U.S. Army Corps of Engineers, Memphis District over approximately 0.23 acres. The project is located near Bird Cemetery, Mississippi County, Missouri, Township 27N, Range 17E, SE 1/4, SE 1/4 of NE 1/4 of Section 22 of the Wickliff Quadrangle. The proposed project includes repairing eroded areas along the levee. A records search and a pedestrian survey failed to locate any prehistoric, historic, or architectural sites within the project right-of-way.

Accession For	
NTIS CRA&I	<input checked="" type="checkbox"/>
DTIC TAB	<input type="checkbox"/>
Unannounced	<input type="checkbox"/>
Justification	
By	
Distribution /	
Availability Codes	
Dist	Avail and/or Special
A-1	

## TABLE OF CONTENTS

<u>Item</u>	<u>Page</u>
Abstract	i
Table of Contents	ii
List of Figures	ii
Introduction	1
Study Area and Project Description	1
Environmental Setting	2
Previous Research	3
Results of the Records Search	3
Survey Methodology and Results	3
Conclusions	4
Bibliography	5

### List of Figures

Figure 1	General Survey Area
Figure 2	Drawing of the Project Area

## Introduction

An intensive cultural resources survey was conducted by Memphis District archaeologists, Jimmy McNeil and Doug Prescott, on 11 June, within the proposed Item No. R-25.3 R.A.C. Levee Repair project right-of-way. The total project includes approximately 0.23 acres. The survey consisted of visual inspection of the proposed borrow area. The pedestrian survey and literature search of this area is in accordance with requirements outlined in the National Historic Preservation Act of 1966 (Public Law 89-665) and recommended to the National Environmental Policy Act of 1969 (Public Law 91-190).

## Study Area and Project Description

The project is located near Bird Cemetery, Mississippi County, Missouri, Township 27N, Range 17E, SE 1/4, SE 1/4 of NE 1/4 of Section 22, of the Wickliffe Quadrangle (Figure 1).

The proposed borrow area showed evidence of having been previously disturbed. Presently the area is covered in young trees. The ground surface was covered with flood deposited silt.

The proposed maintenance action includes rebuilding the damaged levee area. All equipment will be brought in over existing roads and across existing levees and berms. All work and equipment sloping will be conducted from/on the existing levee and berms. Fill materials will be obtained from the project right-of-way.

### Environmental Setting

The project is located within the Mississippi Alluvial lowland of southeast Missouri which is the Mississippi Embayment of the Gulf Coast plain physiographic province (Steiermark 1963:xvi).

Today there are no large areas of woodlands remaining the area; however, there are scattered trees along roads and ditches. The trees are predominantly oak, elm, and sycamore.

Fauna present today includes raccoon, fox, gray squirrel, fox squirrel and opossum. A large population of reptiles, amphibians, fish and birds are also found in the area.

### Previous Research

Until recently, very little archaeological work has been conducted in the general area of this survey, and no work has been conducted in the immediate project area. Recent work within Mississippi County has been conducted by Hopgood (1969), and Williams (1964, 1966, and 1974).

### Results of the Records Search

Mr. Michael Weichman, Chief Archaeologist of the Missouri State Historic Preservation Office, conducted a search of the state files to determine if sites had been recorded for Township 27N, Range 17E, Section 22. By phone, Mr. Weichman informed me that the nearest sites were recorded in Sections 27 (23 Mi 529), 33 (23 Mi 540) and 36 (23 Mi 532). No sites were recorded within the Project right-of-way.

### Survey Methodology and Results

The designated maintenance area right-of-way is approximately 0.23 acres in size. The entire area had been disturbed when the levee was originally built. The survey area consisted of a strip 15.24 meters wide and 60.96 meters long, on the right descending bank. The borrow area was covered with trees but little ground cover. Ground visibility was approximately 60 percent. The ground surface had been recently covered with flood deposited silts. Five subsurface shovel test units (30cm x 30cm x 30cm) indicated that the flood silts extended at least 30cm beneath the surface. No artifacts or other cultural remains were found on the surface or within the shovel test units.

### Conclusions

Based on an in-field cultural resources survey and a background records search, no evidence of significant prehistoric, historic, or architectural resources exists within the direct impact zone of the proposed maintenance work.



## Bibliography

Hopgood, James Finley

- 1969      Continuity and Change in the Baytown Pottery Tradition of the  
Cairo Lowland, Southeast Missouri. Masters Thesis, UMC, 1969.

Steiermark, Julian A.

- 1963      Flora of Missouri. Ames, Iowa: The Iowa State University  
Press.

Weichman, Michael


- 1984      Personal communication.

Williams, J. Raymond

- 1964      A Study of Fortified Indian Villages in S. E. Missouri.  
Prepared for the National Park Service.

- 1966      Land Leveling Salvage Archaeological Work in Southeast  
Missouri: 1966. Prepared for the National Park Service.

- 1974      The Missouri Archeologist, December 1974, Volume 34. The  
Baytown Phases in the Cairo Lowland of Southeast Missouri.  
Columbia, Missouri.



baseline

WICKLIFFE, KY-MO-IL

T. 27N, R. 1E, NE1/4, NE1/4, NE1/4

SEC.

2/12/69

FIGURE 1



PT = 29/11+00  
6

P.C. = 29/13+93

PUSH Repair  
for 20 CUYDAS

29/11+00  
29/11+70±  
29/12+00

Riverside Ramp  
Repair Area  
100 CUYDAS

P.T. = 29/14+81

END OF THE  
29/20+04

300' BORROW

3 E. of Gravelled Road, A  
1/4 Mile, Stamped T.B.  
Gravel Ground

309.42  
304.16  
300.58  
296.83